



APPLICATION TOOLING

INSULATION DISPLACEMENT ASSEMBLY FIXTURES FOR .025" RIBBON CABLE




Arbor Press with Upper Pressing Bar*

CA-120054 (supplied as shown)
CA-120015 or CA-120047 plate is required with this press




Lower Plate Assembly & Upper Pressing Bar

CA-120015
Used with inserts shown on page 156 when terminating .050" cable




Base & Adapter Plate

CA-120047
Used with inserts shown on this page when terminating .025" cable




Adapter Assembly

CA-120058
For use with AMP semiautomatic pneumatic press. NFDS, NFDP Series




ID SCSI Panel Mount Socket

CA-120052
NFDS Series




ID Ultra ATA/UDMA66/100

CA-120064
ATAS Series




ID Transition Plug

CA-120056
NFT, NFT2, NFTSL, MTSL Series




ID SCSI Plug

CA-120053
MDP, NFDP Series



ID Micro Ribbon Socket

CA-120059
MRS Series




ID Socket


CA-120055
NFS Series

APPLICATION TOOLING


INSULATION DISPLACEMENT ASSEMBLY FIXTURES FOR .050" RIBBON CABLE




Arbor Press
CA-120008 (supplied as shown)




ID Socket Insert
CA-120018 IDS2 & FID Series




ID Header Insert
CA-120023 IDH Series
Universal Guide CA-120014 is required with this insert




ID DIP Plug Insert
CA-120017
IDP2 Series




ID Slim Line Plug
CA-120020
IDSL Series



Universal Guide
CA-120014
For use with IDH insert




ID D-Subminiature & Ribbon
CA-120012
DPID, DSID, RPID & RSID Series




ID Transition Plug
CA-120016
IDPB Series


PNEUMATIC PRESS AND ASSEMBLY FIXTURES



Pneumatic Press
CA-120070 (supplied as shown)



Base & Adapter Plate
CA-120047
Required for use with Pneumatic press and inserts



MDRS Insert
CA-120069
MDRS Series